## General Environmental Incident Summary

Incident: 3894 Date/Time Notice: 9/3/2015 1634 DEM Incident No:

Responsible Party: Oneok Rockies Midstream, LLC.

Date Incident:9/2/2015Time Incident:1630Duration:County:McKenzieTwp:149Rng:100Sec:17Qtr:NE

Lat: 47.73214 Long: -103.50830 Method: Navigation quality GPS

Location Description: 22 St NW and 136th Ave NW

Submitted By: Mergaret Clark Affiliation: Jomax

Address: 5047 Jackson St.

City: Williston State: ND Zip: 58801

Received By:

Contact Person: Nadia Kyrylova

2700 Lincoln Avenue SE Sidney, MT 59270

Distance Nearest Occupied Building: 2 Miles Release Contained: Yes

Type of Incident: hose failure

Description of Released Contaminant: Hydraulic Oil

Volume Spilled: 0.90 gallons Ag Related: No

EPA Extremely Hazardous Substance: Unknown Reported to NRC: Unknown

Cause of Incident:
Equipment Hose leak

Risk Evaluation:

none

# of Fatalities: # of Injuries: Affected Medium: 03 - soil

Potential Environmental Impacts:

none

Action Taken or Planned:

Spill contained with absorbent pads and soil collected for disposal.

Wastes Disposal Location: at an approved disposal facility.

Agencies Involved:

## Updates

Date: 9/3/2015 Status: Reviewed; No Followup Required Author: Crowdus, Kory

**Updated Volume:** 

Notes:

Due to small amount released and rapid cleanup, no followup required.